



Les bobines sont rangées/stockées avec deux fils chacune :

- fil noir (20 m) pour les électrodes M et N (P1, P2)
- fil rouge (100 m) pour les électrodes A et B (C1, C2)

Mise en place du sondage :

1. dérouler entièrement les fils noirs ;
2. laisser les fils rouges enroulés sur les bobines, ils se dérouleront au fur et à mesure du sondage ;
3. placer les électrodes aux emplacements voulus (voir feuille de mesure).

Avant chaque mesure

1. connecter les fils sur les électrodes et faire signe que cette opération est finie - **ne plus toucher les électrodes** ;
2. connecter les fils noirs sur le *terrameter* (P1, P2) ;
3. connecter les petits fils rouge de raccord au *terrameter* (C1, C2) - l'autre extrémité ne doit pas être connectée ;
4. modifier les réglages en fonction des espacements $MN/2$ et $AB/2$;
5. connecter les fils de raccord aux bobines ;
6. prévenir que l'injection de courant va avoir lieu.

Après chaque mesure

1. Déconnecter les fils de raccord des bobines et faire signe que le courant ne peut plus circuler ;
2. Déconnecter les fils des électrodes qui ont besoin d'être déplacées - **toujours garder les fiches dans la main** ;
3. Déplacer les électrodes ce qui déroulera les bobines - replanter les électrodes.

Terrameter SAS 1000

PRODUCT LEAFLET

Receiver

| | |
|----------------------------|---|
| Isolation | Input channel is galvanically separated |
| Input Voltage Range | + / - 400 V |
| Input Impedance | 10 MOhm minimum |
| Precision | Better than 0.1 % (in the range 4 - 200 ohm at 1 s integration) |
| Accuracy | 1 % typical |
| Resolution | Theoretical 30 nV |
| Dynamic range | Up to 140 dB plus 64 dB automatic gain (at 1 s integration) |
| Automatic ranging | + / - 2.5 V + / - 10 V + / - 400 V |

Measuring

| | |
|--------------------------------|--------------------------------------|
| Resistivity | YES |
| SP | YES |
| IP | YES |
| Current pulse length | from 0.1 s to 4 s User selectable |
| IP Windows | Up to ten time windows |
| IP integration interval | Up to 8 s |

Transmitter

| | |
|---------------------------------------|--|
| Output power | 100 W |
| Current transmission | True Current Transmitter |
| Output Current Accuracy | Better than 0.5 % at 100 mA |
| Output Current | 1, 2, 5, 10, 20, 50, 100, 200, 500, 1000 mA (operator set or auto ranging) |
| Maximum Output Voltage | +/- 400 V (800 V peak-to-peak) |
| Cycle type in resistivity mode | Plus-Minus-Minus-Plus |
| Cycle type in IP mode | Plus-Zero-Minus-Zero |

General

| | |
|-------------------------|---|
| Casing | Rugged Aluminium case meets IEC IP 66 |
| Computer Display | PC compatible LCD, 200 x 64 pixels, 8 lines of 40 characters |
| I / O ports | Multifunction connector with current and potential including RS232 communication for external devices as PC, LOG and Imaging Banana connectors for current and potential |

With reservations for changes; our products undergo continuous development

| | |
|----------------------------------|---|
| External devices | Lund Imaging System, SAS LOG |
| Memory Capacity | More than 1 500 000 readings |
| Power | Optional Clip-on rechargeable power pack or external 12V DC through SAS-EBA |
| Dimensions (W x L x H) | 105 x 325 x 270 mm with SAS-EBA |
| Weight | 5.1 kg |
| Ambient Temperature Range | - 5°C to + 50 °C operating |

Accessories

Multi-electrode Survey Systems for 2D & 3D

LUND Resistivity & IP Imaging

A centrally switched system for automatic resistivity, IP profiling and vertical imaging.

See LUND brochure for more information

Borehole logging (SAS LOG 300 logging unit)

| | |
|-------------------------------|--------------------|
| Cable length | 300 m |
| Cable markings | Every meter |
| Probe diameter | 40 mm |
| Weight (200 m) | 15 kg |
| Dimensions (W x L x H) | 330 x 750 x 225 mm |

Survey modes and ranges:

| | |
|-------------------------------|--|
| 16" short normal | 0.05 - 100 000 ohmm |
| 64" long normal | 0.5 - 100 000 ohmm |
| 18 feet lateral | 0.5 - 100 000 ohmm |
| Fluid resistivity cell | 0.05 - 100 000 ohmm |
| Self Potential | 0.05 - 1000 mV |
| Temperature | 0°C to + 60°C |
| Temperature precision | +/- 0.01°C (0 - 20°C) +/- 0.1°C (20 - 60°C) |
| Temperature accuracy | +/- 1°C |
| Water level indication | |

Standard field equipment

| | | |
|---|--|------------|
| 1 | ABEM Terrameter SAS 1000 includes: One SAS 1000 Receiver / Transmitter unit One RS232 Cable (9 pin D-sub) One SAS-EBA External Battery Adapter One SAS 1000 Software kit One SAS 1000 Documentation kit | 33 0021 30 |
| 2 | S & W sounding cable set includes: 2 x 250 m cable on reel 2 x 750 m cable on reel 4 x interconnect cable 4 x crocodile clip Transport plywood box | 33 0012 40 |
| 3 | Stainless steel electrode | 33 0012 61 |
| 4 | Non-polarizable electrode | 33 0015 79 |

20121122

Field Equipment

Consult your local ABEM distributor for full details of the various configurations available for you.

ABEM Instrument AB
Löfströms Allé 1
172 66 Sundbyberg, Sweden
www.abem.se

ABEM